

School Property/Block	CERA Region Land Category	Date initial assessment	Initial % NBS	%NBS after temporary strengthening	Final %NBS after permanent strengthening	DEE report date	Comments (if required) & Key Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
<b>Addington (Sacred Heart School)</b>							
Block 1							
Block 2							
Block 3							
Block 1A							
Block 1B							
Block 1D							
Block 4							
<b>Aranui (St James' School)</b>							
Block 1							
Block 2							
Block 3							
Block 4							
Block 8							
Special Needs Facility							
<b>Beckenham (St Peter's School)</b>							
Block 1							
Block 3							
Block 3							
Block 7							
Toilet Block							
<b>Bryndwr (St Patrick's School)</b>							
Block 1							
Block 2 Ground Floor							
Block 2 First Floor							
Library							
Classroom 7							
Classroom 8							
Caretaker							
<b>Burnside (Christ the King School)</b>							
Block 1 Ground Floor							
Block 1 First Floor							
Block 2							
Block 3							
Classroom 10							
Classroom 11							
Garage & Store							

School Property/Block	CERA Region Land Category	Date initial assessment	Initial % NBS	%NBS after temporary strengthening	Final %NBS after permanent strengthening	DEE report date	Comments (if required) & Key Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
<b>Christchurch North (St Mary's School)</b>							
Block 1							
Block 2							
<b>Dallington (St Paul's School)</b>							
Block 1	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 2	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 3	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 4	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 5	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 6	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 7	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 8	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Hall	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Storage/Garage	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Caretaker	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 13	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Portacom moved to Marian College @ Barbadoes St
<b>Hoon Hay (Our Lady of the Assumption School)</b>							
Block 1	TC2/3	15/02/2012	<34%	72%	100%	1/08/2012	Permanent solution currently in the consenting process with the Council
Block 2	TC2/3	1/08/2012	83%	n/a	83%	1/08/2012	
Block 3	TC2/3	1/08/2012	93%	n/a	93%	1/08/2012	
Block 4	TC2/3	1/08/2012	100%	n/a	100%	1/08/2012	
Block 7	TC2/3	1/08/2012	100%	n/a	100%	1/08/2012	
Block 8	TC2/3	1/08/2012	100%	n/a	100%	1/08/2012	
Block 9	TC2/3	1/08/2012	100%	n/a	100%	1/08/2012	
Block 10	TC2/3	1/08/2012	100%	n/a	100%	1/08/2012	
Changing Sheds	TC2/3	1/08/2012	15%	n/a	n/a	1/08/2012	Changing sheds will be demolished
<b>Hornby (St Bernadette's School)</b>							
Block 1	TC1	15/02/2012	<34%	67%	100%	1/08/2012	Design of permanent solution underway
Block 1 (Library)	TC1	1/08/2012	85%	n/a	85%	1/08/2012	
Toilets	TC1	1/08/2012	68%	n/a	tbc	1/08/2012	
Block 3	TC1	1/08/2012	100%	n/a	100%	1/08/2012	
Block 6	TC1	1/08/2012	73%	n/a	73%	1/08/2012	
Block 7	TC1	1/08/2012	100%	n/a	100%	1/08/2012	
Store	TC1	1/08/2012	39%	n/a	tbc	1/08/2012	
<b>Kaipoi (St Patrick's School)</b>							
Block 1 (Juniors)							
Block 2 (Church)							
Block 3							
Block 4							
Block 5							
Block 1A							
Block 7							
Block 1B							

School Property/Block	CERA Region Land Category	Date initial assessment	Initial % NBS	%NBS after temporary strengthening	Final %NBS after permanent strengthening	DEE report date	Comments (if required) & Key Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
<b>Mairehau (Our Lady of Fatima School)</b>							
Block 1 (Ground Floor)							
Block 1 (First Floor)							
Block 3							
Block 4							
Block 5							
Block 6							
Block 7							
Block 8							
Caretaker/Sports Shed							
Garage							
<b>New Brighton (New Brighton Catholic School)</b>							
Block 1							
Block 2							
Block 3							
Block 4							
Block 7							
Block 8							
Toilets							
Storage							
<b>Papanui (St Joseph's School)</b>							
Block 1 (Ground Floor)							
Block 1 (First Floor)							
Block 2							
Block 3							
Block 4							
Block 5							
Block 6							
Block 7							
Block 8							
Block 9							
Block 13							
Caretaker/Sports Shed							
Pool Changing Sheds							
Pool Toilets							
Walkway							

School Property/Block	CERA Region Land Category	Date initial assessment	Initial % NBS	%NBS after temporary strengthening	Final %NBS after permanent strengthening	DEE report date	Comments (if required) & Key Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
-----------------------	---------------------------	-------------------------	---------------	------------------------------------	--	-----------------	---

Rangiora (St Joseph's School)							
Block 1							
Block 2							
Block 3							
Block 4							
Block 5 (Library)							
Storage/Garage							
Covered Walkway							

Riccarton (St Teresa's School)							
Block 1							
Block 2/3							
Versatile Garage / Storage							
Walkway							

Sockburn (Our Lady of Victories School)							
Block 1 (Ground Floor)							
Block 1 (First Floor)							
Block 2/5							
Block 3							
Block 4							
Classroom 10							
Classroom 12							
Caretaker							
Garage/Storage							

St Albans (St Albans Catholic School)							
Block 1 (Area 1)	TC3	1/08/2012	51%	n/a	tbc	1/08/2012	
Block 1 (Area 2)	TC3	1/08/2012	50%	n/a	tbc	1/08/2012	
Block 1 (Area 3)	TC3	1/08/2012	52%	n/a	tbc	1/08/2012	
Block 2	TC3	1/08/2012	83%	n/a	83%	1/08/2012	

Sumner (Our Lady Star of the Sea School)							
Block 1							
Block 2							
Block 3							
Block 4							
Block 5							
Block 1A							
Walkway							

Woolston (St Anne's School)							
Block 1/2/5							
Block 1 (First Floor)							
Block 4							
Block 6							
Block 7							

School Property/Block	CERA Region Land Category	Date initial assessment	Initial % NBS	%NBS after temporary strengthening	Final %NBS after permanent strengthening	DEE report date	Comments (if required) & Key Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
<b>Christchurch City (Catholoic Cathedral College)</b>							
C Block							
D Block							
Skyline Garage (3 Bay)							
G Block							
J Block							
K Block							
Hall (I Block)							
H Block							
New Gymnasium							
Covered Way							
<b>Christchurch City (Marian College @ Barbadoes Street)</b>							
A Block							
B Block							
C Block							
D Block							
G Block							
Portacom Block							
T Block							
Science Block							
Admin Block							
<b>Christchurch North (Marian College @ North Parade)</b>							
Block A (Administration)		3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block B (Forde Block)		3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block C (Common Room)		3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block S (Science)		3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block P		3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block H (Gymnasium)		3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block K (Music)		3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Chapel - (non-integrated)		3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block M (Technology & Library)		3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block G (Caretaker)		3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block T		3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013