School Property/Block	CERA Region	Date initial	Initial	%NBS after	Final %NBS after	DEE	Comments (if required) & Key
	Land Category	assessment	% NBS	temporary strengthening	permanent strengthening	report date	Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
Addington (Sacred Heart School)							
Block 1	TC2	12/04/2013	100%	n/a	100%	12/04/2013	
Block 2	TC2	12/04/2013	45%	n/a	tbc	12/04/2013	
Block 3	TC2	12/04/2013	35%	n/a	tbc	12/04/2013	
Block A1	TC2	12/04/2013	<34%	n/a	n/a	12/04/2013	Toilet block has ben demolished
Block A3	TC2	12/04/2013	15%	n/a	n/a	12/04/2013	Changing sheds (now closed) have reached the end of their economic life and will be demolished
Block A4	TC2	12/04/2013	65%	n/a	tbc	12/04/2013	
Block 4	TC2	12/04/2013	100%	n/a	100%	12/04/2013	
Aranui (St James' School)							
Aranui (St James School) Block 1	TC3	3/09/2012	<34%	35%	tbc	11/12/2012	
Block 2	TC3	11/12/2012	100%	n/a	100%	11/12/2012	
Block 3	TC3	11/12/2012	80%	n/a	80%	11/12/2012	
Block 4	TC3	11/12/2012	100%	n/a	100%	11/12/2012	
Block 5	TC3	11/12/2012	75%	n/a	75%	11/12/2012	
Block 8	TC3	11/12/2012	100%	n/a	100%	11/12/2012	
Special Needs Facility	TC3	11/12/2012	100%	n/a	100%	11/12/2012	
Beckenham (St Peter's School)							
Block 1	TC2/3	20/02/2012	<34%	n/a	n/a	17/08/2012	Block 1 is closed, uneconomic to repair and will be demolished
Block 3 (Senior Classrooms)	TC2/3	17/08/2012	57%	n/a	tbc	17/08/2012	
Block 3 (Library/Principal)	TC2/3	17/08/2012	88%	n/a	88%	17/08/2012	
Block 7 (Changing Sheds)	TC2/3	17/08/2012	15%	n/a	n/a	17/08/2012	Changing sheds (now closed) have reached the end of their economic life and will be demolished
Toilet Block (including the Caretaker's Shed)	TC2/3	17/08/2012	24%	n/a	n/a	17/08/2012	Toilet block (now closed) has reached the end of its economic life and will be demolished
Block 9	TC2/3	17/08/2012	100%	n/a	100%	17/08/2012	
Bryndwr (St Patrick's School)					_		
Block 1 (Classrooms 5&6)	TC2	20/08/2012	40%	n/a	tbc	20/08/2012	
Block 1 (Classroom 4)	TC2	20/08/2012	76%	n/a	76%	20/08/2012	
Block 1 (Administration)	TC2	20/08/2012	100%	n/a	100%	20/08/2012	
Block 2 (Classroom 1)	TC2	20/08/2012	40%	n/a	tbc	20/08/2012	
Block 2 (Classrooms 2&3)	TC2	20/08/2012	34%	n/a	tbc	20/08/2012	
Block 2 (Toilets)	TC2	20/08/2012	62%	n/a	tbc	20/08/2012	
Block 2 (Cloakroom & Teacher's Aide)	TC2	20/08/2012	51%	n/a	tbc	20/08/2012	
Library	TC2	20/08/2012	66%	n/a	tbc	20/08/2012	
Classroom 7	TC2	20/08/2012	100%	n/a	100%	20/08/2012	
Classroom 8	TC2	20/08/2012	77%	n/a	77%	20/08/2012	
Caretaker's Shed	TC2	20/08/2012	100%	n/a	100%	20/08/2012	
Burnside (Christ the King School)							
Block 1 Ground Floor	TC2	9/03/2011	16%	n/a	100%	23/01/2013	Block currently closed and strengthening work has commenced
Block 1 First Floor	TC2	9/03/2011	16%	n/a	100%		Block currently closed and strengthening work has commenced
Block 2	TC2	9/03/2011	11%	n/a	100%	23/01/2013	
Block 3	TC2	23/01/2013	59%	n/a	tbc	23/01/2013	
Classroom 10	TC2	23/01/2013	73%	n/a	73%	23/01/2013	
Classroom 11	TC2	23/01/2013	100%	n/a	100%	23/01/2013	

School Property/Block	CERA Region	Date initial	Initial	%NBS after	Final %NBS after	DEE	Comments (if required) & Key
	Land Category	assessment	% NBS	temporary strengthening	permanent strengthening	report date	Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
				bu enginening		uute	rees a 170 - curriquine proneyrioni 20170 - mai ungeroennie cupuery
Christchurch North (St Mary's School)			-				
Block 1	TC3	15/02/2012	<34%	50%	tbc	21/12/2012	
Block 2	TC3	21/12/2012	100%	n/a	100%	21/12/2012	
Dallington (St Paul's School)							
Block 1	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 2	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 3	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 4	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 5	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 6	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 7	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 8	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Hall	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Storage/Garage	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Caretaker	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 13	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Portacom moved to Marian College @ Barbadoes St
Hoon Hay (Our Lady of the Assumption School)	<b>T</b> (24.19	1.5.00.00.10			1005	4 100 100 4 0	
Block 1	TC2/3	15/02/2012	<34% 83%	72%	>100%	1/08/2012 1/08/2012	Permanent solution complete
Block 2	TC2/3	1/08/2012		n/a	83%		
Block 3	TC2/3	1/08/2012	93%	n/a	93%	1/08/2012 1/08/2012	
Block 4	TC2/3 TC2/3	1/08/2012 1/08/2012	100% 100%	n/a	100%	1/08/2012	
Block 7		1/08/2012	100%	n/a	100%	1/08/2012	
Block 8 Block 9	TC2/3 TC2/3	1/08/2012	100%	n/a n/a	100%	1/08/2012	
Block 9 Block 10	TC2/3	1/08/2012	100%	n/a n/a	100%	1/08/2012	
	TC2/3	1/08/2012	15%	n/a n/a	n/a	1/08/2012	Demolished
Changing Sheds	102/3	1/08/2012	15%	n/a	n/a	1/08/2012	Demonsned
Hornby (St Bernadette's School)							
Block 1	TC1	15/02/2012	<34%	67%	100%	1/08/2012	Permanent solution underway
Block 1 (Library)	TC1	1/08/2012	85%	n/a	85%	1/08/2012	
Toilets	TC1	1/08/2012	68%	n/a	68%	1/08/2012	
Block 3	TC1	1/08/2012	100%	n/a	100%	1/08/2012	
Block 6	TC1	1/08/2012	73%	n/a	73%	1/08/2012	
Block 7	TC1	1/08/2012	100%	n/a	100%	1/08/2012	
Store	TC1	1/08/2012	39%	n/a	tbc	1/08/2012	
Kaiapoi (St Patrick's School)							
Block 1	TC2	13/02/2013	37%	n/a	tbc	13/02/2013	
Block 1 Block 1a	TC2	13/02/2013	100%	n/a	100%	13/02/2013	
Block 1b	TC2	13/02/2013	100%	n/a	100%	13/02/2013	
Block 10 Block 2 (Church)	TC2	13/02/2013	tbc	tbc	tbc	tbc	To be assessed when the detailed assessment of the church is completed
Block 3	TC2	13/02/2013	57%	n/a	tbc	13/02/2013	to be assessed much an actual assessment of the united is completed
Block 4	TC2	13/02/2013	44%	n/a	tbc	13/02/2013	
Block 5 & 6	TC2	13/02/2013	100%	n/a	100%	13/02/2013	
Block 7	TC2	13/02/2013	100%	n/a	100%	13/02/2013	

School Property/Block	CERA Region	Date initial	Initial	%NBS after	Final %NBS after	DEE	Comments (if required) & Key
	Land Category	assessment	% NBS	temporary strengthening	permanent strengthening	report date	Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
		-		strengthening	strengtnening	date	Key: <34% = earthquake prone; Note: 207% = inal target seismic capacity
Mairehau (Our Lady of Fatima School)							
Block 1 (Ground Floor)	TC2	13/11/2012	95%	n/a	95%	13/11/2012	
Block 1 (First Floor)	TC2	13/11/2012	48%	n/a	tbc	13/11/2012	
Block 1 (Classrooms 1, 2, 3)	TC2	1/10/2012	<34%	59%	tbc	13/11/2012	
Block 1 (Classrooms 4, 5, 6)	TC2	13/11/2012	38%	n/a	tbc	13/11/2012	
Block 1 (Withdrawal & WC)	TC2	13/11/2012	64%	n/a	tbc	13/11/2012	
Block 3	TC2	13/11/2012	<34%	35%	tbc	13/11/2012	
Block 4	TC2	13/11/2012	82%	n/a	82%	13/11/2012	
Block 5	TC2	13/11/2012	34%	n/a	tbc	13/11/2012	
Block 6	TC2	13/11/2012	52%	n/a	tbc	13/11/2012	
Block 7	TC2	13/11/2012	100%	n/a	100%	13/11/2012	
Block 8	TC2	13/11/2012	100%	n/a	100%	13/11/2012	
Caretaker/Sports Shed	TC2	13/11/2012	100%	n/a	100%	13/11/2012	
Garage	TC2	13/11/2012	100%	n/a	100%	13/11/2012	
New Brighton (New Brighton Catholic School)							
Block 1	TC2	17/12/2012	36%	n/a	tbc	17/12/2012	
Block 2	TC2	17/12/2012	37%	n/a	tbc	17/12/2012	
Block 3, Area A	TC2	17/12/2012	57%	n/a	tbc	17/12/2012	
Block 3, Area B	TC2	17/12/2012	36%	n/a	tbc	17/12/2012	
Block 4	TC2	17/12/2012	97%	n/a	97%	17/12/2012	
Block 5	TC2	17/12/2012	100%	n/a	100%	17/12/2012	
Block 6	TC2	17/12/2012	100%	n/a	100%	17/12/2012	
Block 7	TC2	17/12/2012	100%	n/a	100%	17/12/2012	
Block 8	TC2	17/12/2012	100%	n/a	100%	17/12/2012	
Papanui (St Joseph's School)							
Block 1 (Ground Floor)	TC2	3/12/2012	34%	n/a	tbc	3/12/2012	
Block 1 (First Floor)	TC2	3/12/2012	42%	n/a	tbc	3/12/2012	
Block 1A	TC2	3/12/2012	59%	n/a	tbc	3/12/2012	
Block 2	TC2	3/12/2012	80%	n/a	80%	3/12/2012	
Block 3	TC2	3/12/2012	<34%	65%	tbc	3/12/2012	
Block 4	TC2	3/12/2012	58%	n/a	tbc	3/12/2012	
Block 5	TC2	3/12/2012	59%	n/a	tbc	3/12/2012	
Block 6	TC2	3/12/2012	59%	n/a	tbc	3/12/2012	
Block 7 & Block 13	TC2	3/12/2012	46%	n/a	tbc	3/12/2012	
Block 8	TC2	3/12/2012	52%	n/a	tbc	3/12/2012	
Block 9	TC2	3/12/2012	100%	n/a	100%	3/12/2012	
Caretaker/Sports Shed	TC2	3/12/2012	100%	n/a	100%	3/12/2012	
Pool Changing Sheds	TC2	3/12/2012	15%	n/a	n/a	3/12/2012	Changing sheds (now closed) have reached the end of their economic life and will be demolished
Pool Toilets	TC2	3/12/2012	15%	n/a	n/a	3/12/2012	Pool toilets (now closed) have reached the end of their economic life and will be demolished

School Property/Block	CERA Region	Date initial	Initial	%NBS after	Final %NBS after	DEE	Comments (if required) & Key
	Land Category	assessment	% NBS	temporary strengthening	permanent strengthening	report date	Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
Rangiora (St Joseph's School)							
Block 1 - Administration	n/a	15/01/2013	100%	n/a	100%	15/01/2013	
Block 1 - Classroom 6	n/a	15/01/2013	93%	n/a	93%	15/01/2013	
Block 2 - Classroom 5	n/a	15/01/2013	37%	n/a	tbc	15/01/2013	
Block 2 - Classrooms 3, 4 & Book Room	n/a	15/01/2013	100%	n/a	100%	15/01/2013	
Block 3	n/a	15/01/2013	100%	n/a	100%	15/01/2013	
Block 4	n/a	15/01/2013	100%	n/a	100%	15/01/2013	
Block 5 (Library)	n/a	15/01/2013	100%	n/a	100%	15/01/2013	
Storage/Garage	n/a	15/01/2013	100%	n/a	100%	15/01/2013	
Riccarton (St Teresa's School)							
Block 1	TC2	5/11/2012	100%	n/a	100%	5/11/2012	
Block 2	TC2	5/11/2012	53%	n/a	tbc	5/11/2012	
Block 3	TC2	5/11/2012	35%	n/a	tbc	5/11/2012	
Block 4	TC2	5/11/2012	100%	n/a	100%	5/11/2012	
Garage	TC2	5/11/2012	100%	n/a	100%	5/11/2012	
						1	
Sockburn (Our Lady of Victories School)							
Block 1	TC1	26/02/2013	56%	n/a	tbc	26/02/2013	
Block 1 A	TC1	26/02/2013	35%	n/a	tbc	26/02/2013	
Block 2/5	TC1	26/02/2013	100%	n/a	100%	26/02/2013	
Block 3	TC1	26/02/2013	79%	n/a	79%	26/02/2013	
Block 4	TC1	26/02/2013	56%	n/a	tbc	26/02/2013	
Block 6	TC1	26/02/2013	100%	n/a	100%	26/02/2013	
Block 8	TC1	26/02/2013	100%	n/a	100%	26/02/2013	
Caretaker	TC1	26/02/2013	100%	n/a	100%	26/02/2013	
Garage/Storage	TC1	26/02/2013	<33%	n/a	n/a	26/02/2013	Demolished
St Albans (St Albans Catholic School)							
Block 1 (Area 1)	TC3	1/08/2012	51%	n/a	tbc	1/08/2012	
Block 1 (Area 2)	TC3	1/08/2012	50%	n/a	tbc	1/08/2012	
Block 1 (Area 3)	TC3	1/08/2012	52%	n/a	tbc	1/08/2012	
Block 2	TC3	1/08/2012	83%	n/a	83%	1/08/2012	
Sumner (Our Lady Star of the Sea School)							
Block 1 & Block 5	TC2	12/09/2012	35%	63%	tbc	24/09/2012	
Block 2	TC2	12/09/2012	<34%	54%	tbc	24/09/2012	
Block 2 Block 3	TC2	24/09/2012	<34% 100%		100%	24/09/2012	
Block 4	TC2	24/09/2012	100%	n/a	100%	24/09/2012	
							·
Woolston (St Anne's School)							
Block 1	TC2	16/08/2012	39%	n/a	tbc	16/08/2012	
Block 1 (First Floor)	TC2	16/08/2012	50%	n/a	tbc	16/08/2012	
Block 2	TC2	16/08/2012	58%	n/a	tbc	16/08/2012	
Block 5	TC2	16/08/2012	37%	n/a	tbc	16/08/2012	
Block 4	TC2	16/08/2012	100%	n/a	100%	16/08/2012	
Block 6	TC2	20/04/2012	7%	n/a	100%	16/08/2012	
Block 7	TC2	16/08/2012	100%	n/a	100%	16/08/2012	

School Property/Block	CERA Region	Date initial	Initial	%NBS after	Final %NBS after	DEE	Comments (if required) & Key
School Property/block	Land Category	assessment	% NBS	temporary	permanent	report	Key: n/a = not applicable; tbc = ≥67% with exact % NBS to be confirmed
				strengthening	strengthening	date	Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
Christchurch City (Catholoic Cathedral College)							
Skyline Garage							
G Block							
J Block							
K Block							
Hall (I Block)							
H Block							
Gymnasium							
L Block							
Covered Way							
Christchurch City (Marian College @ Barbadoes Street)							
A Block							
B Block							
C Block							
D Block							
G Block							
Portacom Block							
T Block							
Science Block							
Admin Block							
Christchurch North (Marian College @ North Parade)							
Block A (Administration)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block B (Forde Block)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block C (Common Room)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block S (Science)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block P	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block H (Gymnasium)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block Fr (Gymasium) Block K (Music)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Chapel - (non-integrated)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013 Geotechnical reassessment in August 2013
Block M (Technology & Library)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block G (Caretaker)	TC3	3/08/2011					
			n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block T	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013

School Property/Block	CERA Region	Date initial	Initial	%NBS after	Final %NBS after	DEE	Comments (if required) & Key
	Land Category	assessment	% NBS	temporary strengthening	permanent strengthening	report date	Key: n/a = not applicable; thc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
				strengthening	strengthening	uate	Key: <54 % = ear inquake prone; Note: 207 % = miar target seising capacity
Greymouth (St Patrick's School)							
Block 1	n/a						
Block 2	n/a						
Covered Way	n/a						
Block 3 (Library / Staffroom)	n/a						
Hokitika (St Mary's School)							
Block 1	n/a						
Hall Ground Floor	n/a						
Hall First Floor	n/a						
Caretaker/Bikeshed	n/a						
Block 5	n/a						
Changing Shed	n/a						
Greymouth (John Paul II High School)							
Block A Ground Floor	n/a						
Block A First Floor	n/a						
Garage	n/a						
Gymnasium Ground Floor	n/a						
Gymnasium First Floor	n/a						
Music Suite	n/a						
Block H	n/a						
Block C	n/a						
Block D Ground Floor	n/a						
Block D First Floor	n/a						
Garage	n/a						

School Property/Block	CERA Region	Date initial	Initial	%NBS after	Final %NBS after	DEE	Comments (if required) & Key	1
	Land Category	assessment	% NBS	temporary strengthening	permanent strengthening	report date	Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity	
			I	*** • • • • • • • • • • • • • • • •				
Ashburton (St Joseph's School)								<u> </u>
Block 1 - Main Block	n/a	25/02/2013	53%	n/a	tbc	25/02/2013	3	<u> </u>
Block 1 - Girls' Conveniences	n/a	25/02/2013	54%	n/a	tbc	25/02/2013	3	<b>_</b>
Block 2	n/a	25/02/2013	75%	n/a	75%	25/02/2013	3	<b>_</b>
Block 4	n/a	25/02/2013	92%	n/a	92%	25/02/2013	3	<u> </u>
Bloc 7 (Storage - 9b)	n/a	25/02/2013	100%	n/a	100%	25/02/2013	3	
Block 8	n/a	25/02/2013	100%	n/a	100%	25/02/2013	3	
Block 9 (Storage Garage - 9a)	n/a	25/02/2013	100%	n/a	100%	25/02/2013		
Block 10	n/a	25/02/2013	100%	n/a	100%	25/02/2013	3	
Block SN	n/a	25/02/2013	100%	n/a	100%	25/02/2013	3	
Fairlie (St Joseph's School)								
Block 1	n/a							
Toilets	n/a							-
Covered Walkway	n/a							
Storage	n/a							+
Block 2	n/a							+
BIOCK 2	n/a							<u> </u>
Methven (Our Lady of the Snows School)								
Block 1	n/a	3/07/2013	34%	n/a	>100%	3/07/2013		
Special Needs	n/a	3/07/2013	>100%	n/a	>100%	3/07/2013		
Block 2	n/a	3/07/2013	>100%	n/a	>100%	3/07/2013		
Storage Shed	n/a	3/07/2013	<34%	n/a	n/a	3/07/2013	Storage shed (now closed) is uneconomic to repair and will be demolished	
Sports Shed	n/a	3/07/2013	>100%	n/a	>100%	3/07/2013		
Block 6	n/a	3/07/2013	>100%	n/a	>100%	3/07/2013		
Pleasant Point (St Joseph's School)								
Block 1	n/a	10/06/2013	>100%	n/a	>100%	10/06/2013		+
		10/06/2013	>100%			10/06/2013		+
Garage	n/a	10/06/2013		n/a	>100%	10/06/2013		+
Administration	n/a	10/06/2013	>100%	n/a	>100%	10/06/2013		<u> </u>
Temuka (St Joseph's School)								
Block 1	n/a							
Block 2	n/a							
Block 3	n/a							<u> </u>
Block 4	n/a							
Block 9 / Store	n/a							<u> </u>
Storage/Shelter	n/a							<u> </u>
Timaru (Sacred Heart School)								
Block 1	n/a							
Storage	n/a							1
Block 2	n/a							1
Block 2 Block 3	n/a							1
Block 3 Block 4	n/a n/a							1
Toilets	n/a							1
Block 5	n/a n/a							+
DIOCK J	n/a					1		

School Property/Block	CERA Region	Date initial	Initial	%NBS after	Final %NBS after	DEE	Comments (if required) & Key
octoor repersyllice	Land Category	assessment	% NBS	temporary	permanent	report	Key: n/a = not applicable; the = 267% with exact % NBS to be confirmed Key: <34% = earthquake prone; Note: 267% = final target seismic capacity
				strengthening	strengthening	date	Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
Timaru North (St Joseph's School)							
Block 1	n/a						
Block 2	n/a						
Block 3	n/a						
Swimming Pool	n/a						
Caretaker/Sports Shed	n/a						
Basement 2/3	n/a						
Block 6 Hall / Multi	n/a						
Waimate (St Patrick's School)							
Block 1							
Block 2							
Block 3							
Block 4							
Storage							
Special Needs							
Changing Shed/Filter							
Timaru (Roncalli College)							
Administration	n/a						
Music Block	n/a						
Library/Chapel Block	n/a						
Science Block*	n/a						
Chanel Block	n/a						
Gymnasium	n/a						
McGuire Block	n/a						
Hall (Ground Floor)	n/a						
Hall (First Floor)	n/a						
McAuley Block (Ground Floor)	n/a						
McAuley Block (First Floor)	n/a						
Ashby Block (Ground Floor)	n/a						
Ashby Block (First Floor)	n/a						
Tech Block (Ground Floor)*	n/a						
Tech Block (First Floor)*	n/a						
Common Room Block (non-integrated)	n/a						
Tuck Shop	n/a						
		1				1	