School Property/Block	CERA Region	Date initial	Initial	%NBS after	Final %NBS after	DEE	Comments (if required) & Key
	Land Category	assessment	% NBS	temporary strengthening	permanent strengthening	report date	Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
				strengthening	strengthening	uate	Rey, C54 / 6 = earthquake prone, Pote. 207 / 6 = final target seising capacity
Addington (Sacred Heart School)							
Block 1							
Block 2							
Block 3							
Block 1A							
Block 1B							
Block 1D							
Block 4							
Aranui (St James' School)							
Block 1							
Block 2						1	
Block 3						 	
Block 4						 	
Block 8							
Special Needs Facility							
Beckenham (St Peter's School)							
Block 1	TC2/3	20/02/2012	<34%	n/a	n/a	17/08/2012	Block 1 is closed, uneconomic to repair and will be demolished
Block 3 (Senior Classrooms)	TC2/3	17/08/2012	57%	n/a	tbc	17/08/2012	brock 1 is cooking the continue to topial and will be demonstrated
Block 3 (Library/Principal)	TC2/3	17/08/2012	88%	n/a	88%	17/08/2012	
Block 7 (Changing Sheds)	TC2/3	17/08/2012	15%	n/a	n/a	17/08/2012	Changing sheds (now closed) have reached the end of their economic life and will be demolished
Toilet Block (including the Caretaker's Shed)	TC2/3	17/08/2012	24%	n/a	n/a	17/08/2012	Toilet block (now closed) has reached the end of its economic life and will be demolished
Block 9	TC2/3	17/08/2012	100%	n/a	100%	17/08/2012	Total of the William Peterson and the State of the Secondaries and that was see demonstrated
S. O. C.	102/3	17700/2012	10070	10 6	10070	17/00/2012	
Bryndwr (St Patrick's School)							
Block 1 (Classrooms 5&6)	TC2	20/08/2012	40%	n/a	tbc	20/08/2012	
Block 1 (Classroom 4)	TC2	20/08/2012	76%	n/a	76%	20/08/2012	
Block 1 (Administration)	TC2	20/08/2012	100%	n/a	100%	20/08/2012	
Block 2 (Classroom 1)	TC2	20/08/2012	40%	n/a	tbc	20/08/2012	
Block 2 (Classrooms 2&3)	TC2	20/08/2012	34%	n/a	tbc	20/08/2012	
Block 2 (Toilets)	TC2	20/08/2012	62%	n/a	tbc	20/08/2012	
Block 2 (Cloakroom & Teacher's Aide)	TC2	20/08/2012	51%	n/a	tbc	20/08/2012	
Library	TC2	20/08/2012	66%	n/a	tbc	20/08/2012	
Classroom 7	TC2	20/08/2012	100%	n/a	100%	20/08/2012	
Classroom 8	TC2	20/08/2012	77%	n/a	77%	20/08/2012	
Caretaker's Shed	TC2	20/08/2012	100%	n/a	100%	20/08/2012	
Burnside (Christ the King School)							
Block 1 Ground Floor						1	
Block 1 First Floor						1	
Block 2						 	
Block 3							
Classroom 10						-	
Classroom 11						-	
Garage & Store							

School Property/Block	CERA Region Land Category	Date initial assessment	Initial % NBS	%NBS after temporary strengthening	Final %NBS after permanent strengthening	DEE report date	Comments (if required) & Key Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
Christchurch North (St Mary's School)							
Block 1							
Block 2						<u> </u>	
Dallington (St Paul's School)							
Block 1	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 2	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 3	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 4	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 5	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 6	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 7	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 8	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Hall	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Storage/Garage	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Caretaker	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 13	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Portacom moved to Marian College @ Barbadoes St
Hoon Hay (Our Lady of the Assumption School)							
Block 1	TC2/3	15/02/2012	<34%	72%	100%	1/08/2012	Permanent solution consented by the Council
Block 2	TC2/3	1/08/2012	83%	n/a	83%	1/08/2012	
Block 3	TC2/3	1/08/2012	93%	n/a	93%	1/08/2012	
Block 4	TC2/3	1/08/2012	100%	n/a	100%	1/08/2012	
Block 7	TC2/3	1/08/2012	100%	n/a	100%	1/08/2012	
Block 8	TC2/3	1/08/2012	100%	n/a	100%	1/08/2012	
Block 9	TC2/3	1/08/2012	100%	n/a	100%	1/08/2012	
Block 10	TC2/3	1/08/2012	100%	n/a	100%	1/08/2012	
Changing Sheds	TC2/3	1/08/2012	15%	n/a	n/a	1/08/2012	Changing sheds (now closed) have reached the end of their economic life and will be demolished
Hornby (St Bernadette's School)							
Block 1	TC1	15/02/2012	<34%	67%	100%	1/08/2012	Design of permanent solution completed
Block 1 (Library)	TC1	1/08/2012	85%	n/a	85%	1/08/2012	
Toilets	TC1	1/08/2012	68%	n/a	tbc	1/08/2012	
Block 3	TC1	1/08/2012	100%	n/a	100%	1/08/2012	
Block 6	TC1	1/08/2012	73%	n/a	73%	1/08/2012	
Block 7	TC1	1/08/2012	100%	n/a	100%	1/08/2012	
Store	TC1	1/08/2012	39%	n/a	tbc	1/08/2012	
Kaiapoi (St Patrick's School)							
Block 1 (Juniors)							
Block 2 (Church)							
Block 3							
Block 4							
Block 5							
Block 1A							
Block 7						-	
Block 1B						1	

School Property/Block	CERA Region	Date initial	Initial	%NBS after	Final %NBS after	DEE	Comments (if required) & Key
	Land Category	assessment	% NBS	temporary	permanent	report	Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
				strengthening	strengthening	date	Key: <54% = earthquake prone; Note: ≥67% = final target seismic capacity
Mairehau (Our Lady of Fatima School)							
Block 1 (Ground Floor)							
Block 1 (First Floor)							
Block 3							
Block 4							
Block 5							
Block 6							
Block 7							
Block 8							
Caretaker/Sports Shed							
Garage							
New Brighton (New Brighton Catholic School)							
Block 1							
Block 2							
Block 3							
Block 4							
Block 7							
Block 8							
Toilets							
Storage							
Papanui (St Joseph's School)							
Block 1 (Ground Floor)							
Block 1 (First Floor)							
Block 2							
Block 3							
Block 4							
Block 5							
Block 6							
Block 7							
Block 8							
Block 9							
Block 13							
Caretaker/Sports Shed							
Pool Changing Sheds							
Pool Toilets							
Walkway							

School Property/Block	CERA Region	Date initial	Initial	%NBS after	Final %NBS after		Comments (if required) & Key
	Land Category	assessment	% NBS	temporary strengthening	permanent strengthening	report date	Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
Rangiora (St Joseph's School)							
Block 1							
Block 2							
Block 3							
Block 4							
Block 5 (Library)							
Storage/Garage							
Covered Walkway							
Riccarton (St Teresa's School)							
Block 1							
Block 2/3							
Versatile Garage / Storage							
Walkway							
marray							
Sockburn (Our Lady of Victories School)							
Block 1 (Ground Floor)							
Block 1 (First Floor)							
Block 2/5							
Block 3							
Block 4							
Classroom 10							
Classroom 12							
Caretaker							
Garage/Storage							
St Albans (St Albans Catholic School)	maa.	1/00/2012	510/	,	a	1/00/2012	
Block 1 (Area 1)	TC3	1/08/2012	51%	n/a	tbc	1/08/2012	
Block 1 (Area 2)	TC3	1/08/2012	50%	n/a	tbc	1/08/2012	
Block 1 (Area 3)	TC3	1/08/2012	52%	n/a	tbc	1/08/2012	
Block 2	TC3	1/08/2012	83%	n/a	83%	1/08/2012	
Sumner (Our Lady Star of the Sea School)							
Block 1 & Block 5	TC2	12/09/2012	35%	63%	tbc	24/09/2012	
Block 2	TC2	12/09/2012	<34%	54%	tbc	24/09/2012	
Block 3	TC2	24/09/2012	100%	n/a	100%	24/09/2012	
Block 4	TC2	24/09/2012	100%	n/a	100%	24/09/2012	
Woolston (St Anne's School)							
Block 1	TC2	16/08/2012	39%	n/a	tbc	16/08/2012	
Block 1 (First Floor)	TC2	16/08/2012	50%	n/a	tbc	16/08/2012	
Block 2	TC2	16/08/2012	58%	n/a	tbc	16/08/2012	
Block 5	TC2	16/08/2012	37%	n/a	tbc	16/08/2012	
Block 4	TC2	16/08/2012	100%	n/a	100%	16/08/2012	
Block 6	TC2	20/04/2012	7%	n/a	100%	16/08/2012	
Block 7	TC2	16/08/2012	100%	n/a	100%	16/08/2012	

School Property/Block	CERA Region	Date initial	Initial	%NBS after	Final %NBS after	DEE	Comments (if required) & Key
	Land Category	assessment	% NBS	temporary	permanent	report	Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed
				strengthening	strengthening	date	Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
Christchurch City (Catholoic Cathedral College)							
Skyline Garage							
G Block							
J Block							
K Block							
Hall (I Block)							
H Block							
Gymnasium							
L Block							
Covered Way							
Christchurch City (Marian College @ Barbadoes Street)							
A Block							
B Block							
C Block							
D Block							
G Block							
Portacom Block							
T Block							
Science Block							
Admin Block							
Christchurch North (Marian College @ North Parade)							
Block A (Administration)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block B (Forde Block)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block C (Common Room)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block S (Science)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block P	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block H (Gymnasium)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block K (Music)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Chapel - (non-integrated)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block M (Technology & Library)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block G (Caretaker)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block T	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013