School Property/Block	CERA Region	Date initial	Initial	%NBS after	Final %NBS after	DEE	Comments (if required) & Key
	Land Category	assessment	% NBS	temporary	permanent	report	Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed
				strengthening	strengthening	date	Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
Addington (Sacred Heart School)							
Block 1							
Block 2							
Block 3							
Block 1A							
Block 1B							
Block 1D							
Block 4							
Aranui (St James' School)							
Block 1							
Block 2							
Block 3	1						
Block 4							
Block 8	-						
Special Needs Facility							
Beckenham (St Peter's School)							
Block 1	TC2/3	20/02/2012	<34%	n/a	n/a	17/09/2012	Block 1 is closed, uneconomic to repair and will be demolished
Block 3 (Senior Classrooms)	TC2/3	17/08/2012	57%	n/a	tbc	17/08/2012	Brock 1 is closed, unconforme to repair and will be definitished
			88%		88%	17/08/2012	
Block 3 (Library/Principal) Block 7 (Changing Sheds)	TC2/3 TC2/3	17/08/2012 17/08/2012	15%	n/a			Changing sheds (now closed) have reached the end of their economic life and will be demolished
Toilet Block (including the Caretaker's Shed)	TC2/3	17/08/2012	24%	n/a n/a	n/a n/a		Toilet block (now closed) has reached the end of its economic life and will be demolished
Block 9	TC2/3	17/08/2012	100%		100%	17/08/2012	Tonet block (now closed) has reached the end of its economic life and will be demonstred
DIOCK 9	102/3	17/08/2012	100%	n/a	100%	17/06/2012	
Bryndwr (St Patrick's School)							
Block 1 (Classrooms 5&6)	TC2	20/08/2012	40%	n/a	tbc	20/08/2012	
Block 1 (Classroom 4)	TC2	20/08/2012	76%	n/a	76%	20/08/2012	
Block 1 (Administration)	TC2	20/08/2012	100%	n/a	100%	20/08/2012	
Block 2 (Classroom 1)	TC2	20/08/2012	40%	n/a	tbc	20/08/2012	
Block 2 (Classrooms 2&3)	TC2	20/08/2012	34%	n/a	tbc	20/08/2012	
Block 2 (Toilets)	TC2	20/08/2012	62%	n/a	tbc	20/08/2012	
Block 2 (Cloakroom & Teacher's Aide)	TC2	20/08/2012	51%	n/a	tbc	20/08/2012	
Library	TC2	20/08/2012	66%	n/a	tbc	20/08/2012	
Classroom 7	TC2	20/08/2012	100%	n/a	100%	20/08/2012	
Classroom 8	TC2	20/08/2012	77%	n/a	77%	20/08/2012	
Caretaker's Shed	TC2	20/08/2012	100%	n/a	100%	20/08/2012	
Burnside (Christ the King School)							
Block 1 Ground Floor							
Block 1 First Floor							
Block 2							
Block 3							
Classroom 10							
Classroom 11							
Garage & Store	1						

School Property/Block	CERA Region Land Category	Date initial assessment	Initial % NBS	%NBS after temporary	Final %NBS after permanent	DEE report	Comments (if required) & Key Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed
				strengthening	strengthening	date	Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
Christchurch North (St Mary's School)							
Block 1							
Block 2							
Dallington (St Paul's School)							
Block 1	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 2	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 3	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 4	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 5	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 6	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 7	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 8	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Hall	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Storage/Garage	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Caretaker	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Red Zone
Block 13	Red Zone	29/01/2011	n/a	n/a	n/a	n/a	Portacom moved to Marian College @ Barbadoes St
Hoon Hay (Our Lady of the Assumption School)							
Block 1	TC2/3	15/02/2012	<34%	72%	100%	1/08/2012	Permanent solution currently in the consenting process with the Council
Block 2	TC2/3	1/08/2012	83%	n/a	83%	1/08/2012	
Block 3	TC2/3	1/08/2012	93%	n/a	93%	1/08/2012	
Block 4	TC2/3	1/08/2012	100%	n/a	100%	1/08/2012	
Block 7	TC2/3	1/08/2012	100%	n/a	100%	1/08/2012	
Block 8	TC2/3	1/08/2012	100%	n/a	100%	1/08/2012	
Block 9	TC2/3	1/08/2012	100%	n/a	100%	1/08/2012	
Block 10	TC2/3	1/08/2012	100%	n/a	100%	1/08/2012	
Changing Sheds	TC2/3	1/08/2012	15%	n/a	n/a	1/08/2012	Changing sheds (now closed) have reached the end of their economic life and will be demolished
Hornby (St Bernadette's School)							
Block 1	TC1	15/02/2012	<34%	67%	100%	1/08/2012	Design of permanent solution underway
Block 1 (Library)	TC1	1/08/2012	85%	n/a	85%	1/08/2012	
Toilets	TC1	1/08/2012	68%	n/a	tbc	1/08/2012	
Block 3	TC1	1/08/2012	100%	n/a	100%	1/08/2012	
Block 6	TC1	1/08/2012	73%	n/a	73%	1/08/2012	
Block 7	TC1	1/08/2012	100%	n/a	100%	1/08/2012	
Store	TC1	1/08/2012	39%	n/a	tbc	1/08/2012	
Kaiapoi (St Patrick's School)							
Block 1 (Juniors)							
Block 2 (Church)							
Block 3							
Block 4							
Block 1A Block 7 Block 1B							

	Lorent P	D	Y 1/1 1	A/NIDG 6	FI 10/NTC 6	DEE	In
School Property/Block	CERA Region Land Category	Date initial assessment	Initial % NBS	%NBS after temporary	Final %NBS after permanent	DEE report	Comments (if required) & Key Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed
	Zana Category	шореоритен	701120	strengthening	strengthening	date	Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
Mairehau (Our Lady of Fatima School)							
Block 1 (Ground Floor)							
Block 1 (First Floor)							
Block 3							
Block 4							
Block 5							
Block 6							
Block 7							
Block 8							
Caretaker/Sports Shed							
Garage							
New Brighton (New Brighton Catholic School)							
Block 1							
Block 2							
Block 3							
Block 4							
Block 7							
Block 8							
Toilets							
Storage							
Papanui (St Joseph's School)							
Block 1 (Ground Floor)							
Block 1 (First Floor)							
Block 2							
Block 3							
Block 4							
Block 5							
Block 6							
Block 7							
Block 8							
Block 9							
Block 13							
Caretaker/Sports Shed							
Pool Changing Sheds							
Pool Toilets							
Walkway							

School Property/Block	CERA Region	Date initial	Initial	%NBS after	Final %NBS after	DEE	Comments (if required) & Key]
	Land Category	assessment	% NBS	temporary strengthening	permanent strengthening	report date	Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity	
Rangiora (St Joseph's School)								
Block 1								
Block 2								
Block 3								
Block 4								
Block 5 (Library)								
Storage/Garage								
Covered Walkway								
Riccarton (St Teresa's School)]
Block 1								
Block 2/3								
Versatile Garage / Storage								
Walkway								
								- 1
Sockburn (Our Lady of Victories School)								
Block 1 (Ground Floor)								
Block 1 (First Floor)								
Block 2/5								
Block 3								
Block 4								
Classroom 10								
Classroom 12								
Caretaker								
Garage/Storage								
St Albans (St Albans Catholic School)								
Block 1 (Area 1)	TC3	1/08/2012	51%	n/a	tbc	1/08/2012		
Block 1 (Area 2)	TC3	1/08/2012	50%	n/a	tbc	1/08/2012		
Block 1 (Area 3)	TC3	1/08/2012	52%	n/a	tbc	1/08/2012		
Block 2	TC3	1/08/2012	83%	n/a	83%	1/08/2012		
								1
Sumner (Our Lady Star of the Sea School)								
Block 1								
Block 2								
Block 3								
Block 4								
Block 5								
Block 1A								
Walkway								
Woolston (St Anne's School)								1
Block 1	TC2	16/08/2012	39%	n/a	tbc	16/08/2012		
Block 1 (First Floor)	TC2	16/08/2012	50%	n/a	tbc	16/08/2012		
Block 1 (First Floor) Block 2	TC2	16/08/2012	58%	n/a n/a	tbc	16/08/2012		•
Block 5	TC2	16/08/2012	37%	n/a n/a	tbc	16/08/2012		1
Block 4	TC2	16/08/2012	100%		100%	16/08/2012		•
				n/a		16/08/2012		1
Block 6	TC2	20/04/2012	7%	n/a	100%	16/08/2012		-
Block 7	TC2	16/08/2012	100%	n/a	100%	16/08/2012		J

School Property/Block	CERA Region	Date initial	Initial	%NBS after	Final %NBS after	DEE	Comments (if required) & Key
School 11 Operty/Block	Land Category	assessment	% NBS	temporary	permanent	report	Key: n/a = not applicable; tbc = ≥67% with exact %NBS to be confirmed
				strengthening	strengthening	date	Key: <34% = earthquake prone; Note: ≥67% = final target seismic capacity
Christchurch City (Catholoic Cathedral College)							
Skyline Garage							
G Block							
J Block							
K Block							
Hall (I Block)							
H Block							
Gymnasium							
L Block							
Covered Way							
Christchurch City (Marian College @ Barbadoes Street)							
A Block							
B Block	+						
C Block	+						
D Block	+						
G Block	+						
Portacom Block	+						
T Block	1						
Science Block	1						
Admin Block							
Christchurch North (Marian College @ North Parade)							
Block A (Administration)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block B (Forde Block)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block C (Common Room)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block S (Science)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block P	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block H (Gymnasium)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block K (Music)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Chapel - (non-integrated)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block M (Technology & Library)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block G (Caretaker)	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013
Block T	TC3	3/08/2011	n/a	n/a	n/a	n/a	Geotechnical reassessment in August 2013